Qty:

10 Um:

Each

Date:

Tuesday, 29/04/2008 3:10:16 PM

User:

Julie Lecocq

Process Sheet

Drawing Name

Part Number

Material **Due Date**

Drawing Number

Project Number

Drawing Revision

: D2648-3

: D26483

: R08-026

: 06/05/2008

Customer

: CC-DAR01 Dart Aerospace Ltd.

S.O. No. :

: SMALL /MED FAB

Type

Job Number

: 38886

Estimate Number

: 10804

P.O. Number

This Issue : 29/04/2008

: NC

First Issue : //

: 00015 **Previous Run**

Written By

Prsht Rev.

Comment

:JUD84.29 Checked & Approved By

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

D26483



Comment: Qty.:

1.0000 Each(s)/Unit Total:

10.0000 Each(s)

Wearpad

Wearpad

Original B33992

QC5 2.0

INSPECT WORK TO QURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

3.0

4.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify with a the new Batch #, and restock.

Location:

QC21





Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



U 5/205.08

18/05/09/

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE	STEP	PRO	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No:		PAR #:	Fault Category: N			R: Yes No DQA: Date:					
							QA: N/C Closed: Date:				
NCR:		V	WORK ORDE	R NON-CONFORM	ANCE (I	NCR)					
DATE	STEP	Description of NC Section A	Corrective Action Section		tion B		Verification		Approval	Approval	
			Initial Chief Eng	Action Description Chief Eng		ign & Date	Section C		Chief Eng	QC Inspector	
					,						

NOTE: Date & initial all entries